



103,10	103,20	104,50	104,00	103,70	103,70	103,80	104,10	104,30	104,50	104,50	104,40	104,00	103,70	103,60
103,35	103,50	104,43	104,36	104,07	104,10	104,23	104,38	104,58	104,71	104,69	104,62	104,45	104,07	103,94

R = 650 T = 11,0 B = 0,09			R = 950 T = 25,0 B = 0,33			R = 2100 T = 25,0 B = 0,15			0,7		0,6		0,7		0,7		-0,1		-0,3		-1,0		-1,2		R = 2500 T = 25,0 B = 0,13				
0,3		3,7		-1,6		-1,8		0,6		0,7		0,6		0,7		0,7		-0,1		-0,3		-1,0		-1,2		-1,1		0,9	
25		36		25		25		30		20		25		30		20		25		25		18		32		25		25	
371		407		432		457		487		507		532		562		582		607		632		650		682		707		732	




103,80	104,03
104,20	104,23
104,20	104,37
103,94	104,25
103,80	104,12
103,50	103,79
103,30	103,46
102,90	103,13
103,10	103,19
103,04	103,24
103,00	103,28
103,10	103,33
102,80	103,33
103,10	103,42
103,70	103,85
103,80	103,99
103,80	104,12

0,8	R = 1500 T = 16,0 B = 0,08		-1,5	-1,3	-1,3	-1,3	0,3	0,3	0,4	0,2	0,0	R = 2600 T = 25,0 B = 0,12		0,5	0,5	0,4
	0,9	-1,2										-0,1	1,8			
25	25	16	9	25	25	25	25	16	12	25	25	25	31	26	25	25
757	782	798	807	832	857	882	907	923	935	960	985	1010	1041	1067	1092	1117




104,00	104,23
103,90	104,18
103,90	104,14
104,20	104,47
104,60	104,73
104,40	104,78
104,40	104,73
104,40	104,69
104,40	104,65
104,40	104,73
104,60	104,84
104,10	104,58
103,80	104,29
103,80	104,14
104,00	104,18

-0,2	-0,2	1,4	R = 3000 T = 25,0 B = 0,11		-0,2	-0,2	-0,2	0,4	0,4	-1,1	-1,1	R = 3000 T = 25,0 B = 0,11		R = 28 T = 25 B = 0,1
25	28	23	1,4	-0,3	25	25	25	25	25	25	25	-1,1	0,6	0,7
1142	1170	1193	1220	1245	1270	1295	1320	1345	1370	1395	1420	1445	1470	1495



104,10	104,25
103,80	104,07
103,60	103,85
103,30	103,69
103,40	103,83
103,80	104,14
104,20	104,47
104,50	104,63
104,30	104,51
104,10	104,36
104,00	104,27
103,60	103,94
103,30	103,63
103,10	103,39
102,90	103,34
103,30	103,66
103,90	104,16

300 25,0 0,11	<div><div></div><div>-1,1</div><div>20</div></div>	<div><div>R = 2300 T = 25,0 B = 0,14</div><div></div><div>-1,1</div><div>1,1</div><div>28</div><div>25</div></div>		1,2	1,3	<div><div>R = 2400 T = 25,0 B = 0,13</div><div></div><div>1,1</div><div>-1,0</div><div>25</div><div>25</div></div>		-0,9	-1,1	-1,3	-1,2	-1,2	<div><div>R = 1850 T = 25,0 B = 0,17</div><div></div><div>-0,8</div><div>1,9</div><div>29</div><div>25</div></div>		2,0	<div><div></div><div>R = 1 T = B =</div><div></div><div>2,0</div><div>25</div></div>	
		-1,1	1,1			1,1	-1,0						-0,8	1,9		2,0	
	25	20	28	25	25	25	25	25	17	8	25	25	21	29	25	25	25
1520	1540	1568	1593	1618	1643	1668	1693	1710	1718	1743	1768	1789	1818	1843	1868	1893	



PRZEPUST BEZ PRZEBUDOWY

104,47	104,36	104,01	103,85	103,85	104,10	104,34	104,43	104,71	104,84	105,04	105,13	104,98	104,40	103,61	101,98	101,10	100,73
104,40	104,10	103,70	103,50	103,50	103,85	104,09	104,20	104,41	104,55	104,80	104,90	104,70	104,00	103,50	101,70	100,60	100,50

550 25,0 0,20	<div><div></div></div> -1,4	<div><div></div></div> -1,3	<div><div></div></div> <div>R = 2800 T = 25,0 B = 0,11</div>		<div><div></div></div> 1,4	<div><div></div></div> 1,2	<div><div></div></div> 1,3	<div><div></div></div> 0,9	<div><div></div></div> 0,8	<div><div></div></div> 0,7	<div><div></div></div> -0,8	<div><div></div></div> -2,3	<div><div></div></div> <div>R = 1450 T = 25,0 B = 0,22</div>		<div><div></div></div> <div>R = 900 T = 22,0 B = 0,26</div>		<div><div></div></div> 0,4
	-1,2			-0,4	1,4									-2,3	-5,8	-5,2	-0,4
25	25	12	28	25	17	8	21	14	25	12	20	25	25	32	22	28	10
1918	1943	1955	1983	2008	2025	2033	2054	2068	2093	2105	2125	2150	2175	2207	2229	2257	2267

